

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU23649/15	12/03/2015 Thursday 07:30	B2039 Jct B2039	B2039 OCKHAM ROAD NORTH AT ROUNDABOUT JUNCTION WITH A3 OCKHAM	V2 HAS NOT LOOKED AHEAD AS SHE PULLED OUT AND DROVE INTO R/O V1

Grid Ref: 506212 157370

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Waiting to go ahead-held up	SE-NW	Back	N	63	Drv		Slight	M	63
Car	Waiting to go ahead-held up	SE-NW	Front	N	52	Drv		Slight	F	52

GU73697/12	08/09/2012 Saturday 15:12	B2039	OUTSIDE 'TANKARDS' B2039 OCKHAM ROAD NORTH OCKHAM	V1 TRAVELLING BEHIND V2. V2 SLOWING TO TURN LEFT INTO PRIVATE DRIVEWAY. V1 FAILED TO STOP IN TIME AND COLLIDED WITH REAR OF V2.
------------	---------------------------------	-------	--	---

Grid Ref: 506522 156880

Jct Type: Private Dr/Entrance
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: LIGHT-No Street lights
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 308 Following too close
V001 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	SE-NW	Front	N	68	Drv		Slight	M	68
Car	Turning Left	SE-SW	Back	N	44					

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident						
GU01710/12	06/12/2012 Thursday 07:29	B2039	B2039 OCKHAM ROAD NORTH O/S TANKARDS OCKHAM	V1 HAS LOST CONTROL ON ICY ROAD AND COLLIDED HEAD ON WITH V2.						
Grid Ref: 506538 156865										
Jct Type: ~Not at jct(or 20m from)										
Jct Control:										
Speed Limit: 30 mph										
Site Conditions		Contributory Factors :								
Light:	DARK-No street lights	V001 103 Slippery road (due to weather)								
R.S.C.:	Frost/Ice	V001 410 Loss of control								
Weather:	Other weather									
C/way Haz:	~None									
Spec Cond:	~None									
VEHICLES:										
Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead right hand bend	SE-NW	None	Y	23	Drv		Slight	F	23
Car	Going ahead left hand bend	NW-SE	None	N	25					

GU05774/13	06/05/2013 Monday 08:28	B2039	B2039 OCKHAM ROAD OUTSIDE 'TANKARDS' OCKHAM	V1 TRAVELLING FROM OCKHAM VILLAGE HAS LEFT CARRIAGEWAY TO NEARSDIE COLLIDING WITH WALL OUTSIDE 'TANKARDS'.
Grid Ref: 506524 156879				

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 40 mph

Site Conditions

Light: Daylight

R.S.C.: Dry

Weather: Fine (no high wind)

C/way Haz: ~None

Spec Cond: ~None

Contributory Factors :

V001 503 Fatigue

V001 410 Loss of control

VEHICLES:					CASUALTIES:					
Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	SE-NW	Front	N	46	Drv		Serious	M	46

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU15818/14	04/06/2014 Wednesday 07:58	B2039	B2039 OCKHAM ROAD NORTH OUTSIDE 'HERMISTON' OCKHAM	V2 STATIONARY ABOUT TO TURN INTO DRIVE WHEN V1 A POLICE VEHICLE ON BLUES OVERTOOK V2 AND VEHICLES COLLIDED

Grid Ref: 509014 154814

Jct Type: Private Dr/Entrance
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 903 Emergency vehicle on call
V002 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	O/taking moving Veh on o/side	NW-SE	N/side	N	28	Pas		Slight	F	30
Car	Turning Right	NW-SW	Front	N	48					

GU86846/16	14/07/2016 Thursday 08:50	B2039	B2039 OCKHAM ROAD NORTH EAST HORSLEY	V1 HAS HIT PEDESTRIAN AND FTS
------------	---------------------------------	-------	---	-------------------------------

Grid Ref: 509052 154755

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 406 Failed to judge other person's path or

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	SE-NW	N/side	N	71	Ped	Stat	Slight	M	40

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU84276/16	23/06/2016 Thursday 11:05	B2039 Jct D	B2039 OCKHAM ROAD SOUTH AT JUNCTION WITH STATION APPROACH EAST HORSLEY	PEDESTRIAN C1 HAS WALKED OUT INTO CARRIAGEWAY AND BEEN STRUCK BY V1.

Grid Ref: 509214 154361

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

C001 806 Pedestrian impaired by alcohol
C001 802 Pedestrian failed to look properly
C001 804 Wrong use of pedestrian crossing

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	N-S	Front	N	82	Ped	W	Slight	M	44

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU84890/16	07/07/2016 Thursday 17:06	B2039 Jct D	B2039 OCKHAM ROAD SOUTH AT JUNCTION WITH KINGSTON AVENUE EAST HORSLEY	V1 TURNING RIGHT FAILED TO SEE V2 AND DROVE INTO PATH CAUSING A COLLISION. V3 HAS APPROACHED AS THE COLLISION OCCURRED AND HAS COLLIDED WITH V2

Grid Ref: 509215 154363

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Turning Right	W-S	Front	N	20					
Car	Going ahead other	E-W	Front	N	25	Drv		Slight	F	25

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU55862/17	24/01/2017 Tuesday 10:38	B2039	B2039 OCKHAM SOUTH ROAD EAST HORSLEY Grid Ref: 509219 154350	VEHICLE 1 HAS BEEN TRAVELLING NORTH TO SOUTH ALONG OCKHAM ROAD SOUTH. A CASH IN TRANSIT VAN WAS PARKED TAKING CASH INTO THE BANK OBSTRUCTING THE PATH OF ONCOMING VEHICLES. VEHICLE 1 HAS STOPPED TO ALLOW ONCOMING VEHICLES TO PASS AROUND THE CASH VAN. VEHICLE 2 STOPPED BEHIND VEHICLE 1. VEHICLE 3
Jct Type: ~Not at jct(or 20m from)				
Jct Control:				
Speed Limit: 30 mph				

Site Conditions

Light: Daylight
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V003 405 Failed to look properly
V003 406 Failed to judge other person's path or

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Waiting to go ahead-held up	N-S	Back	N	48	Drv		Slight	F	48
Car	Waiting to go ahead-held up	N-S	Back	N	69	Pas		Slight	F	12
Car	Going ahead other	N-S	Front	N	22	Drv		Slight	F	22

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU20887/15	06/01/2015 Tuesday 17:00	B2039	OCKHAM ROAD SOUTH EAST HORSLEY Grid Ref: 509245 154268	V1 HAS COLLIDED WITH PEDESTRIAN ON CROSSING.

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: DARK-Street Lighting -LIT
R.S.C.: Dry
Weather: Fine with High Winds
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	N-S	Front	N	68	Ped	E	Slight	F	59

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU62517/17	16/02/2017 Thursday 11:45	B2039 Jct D	B2039 OCKHAM ROAD SOUTH AT JUNCTION WITH STATION PARADE EAST HORSLEY	VEHICLE 1 HAS PULLED OUT IN FRONT OF CYCLIST.

Grid Ref: 509251 154252

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Starting	E-N	O/side	N	74					
P/C	Going ahead other	S-N	Front	N	19	Drv		Slight	M	19

GU70935/12	27/05/2012 Sunday 14:09	B2039 Jct D	B2039 OCKHAM ROAD SOUTH 20 METRES SOUTH OF OLD RECTORY LANE HORSLEY	V1 AND V2 TRAVELLING ON NARROW ROAD. V1 SLOWS FOR TRAFFIC. V2 HITS V1.
------------	-------------------------------	----------------	---	---

Grid Ref: 509319 154058

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: LIGHT-No Street lights
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 406 Failed to judge other person's path or
V002 408 Sudden braking

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NW-SE	Front	N	46					
Car	Slowing or Stopping	NW-SE	Back	N	33	Pas		Slight	F	30

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU73060/12	16/08/2012 Thursday 17:19	B2039 Jct D	OUTSIDE DUNSTER ROMELLI OCKHAM ROAD NORTH AT JUNCTION WITH GUILSHILL Grid Ref: 506906 156638	V1 (MOTORBIKE) AND V2 TRAVELLING ON A3 TOWARDS EAST HORSLEY. V2 STATIONARY INDICATING TO TURN RIGHT. V1 ATTEMPTED TO PASS V2 TO THE NEAR SIDE LOST FRONT WHEEL UNDER BRAKING. V1 DRIVER LANDED ON PAVEMENT CAUSING INJURY.

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: LIGHT-No Street lights
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 403 Poor turn or manoeuvre
V001 605 Inexperienced or learner driver/rider
V001 410 Loss of control

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
M/C125-500 Car	Overtaking on nearside Waiting to turn Right	W-E W-S	Back None	N N	52 48	Drv		Serious	M	52

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU01308/12	21/12/2012 Friday 13:08	B2039 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM ROAD RIPLEY Grid Ref: 506132 157460	V1 IN LANE 1 ON R/ABOUT AND V2 IS IN LANE 2. V2 HAS SUDDENLY SWERVED RIGHT CAUSING V1 TO AVOID IT. V1 HAS THEN LOST CONTROL AND HAS HIT AN EMBANKMENT

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 60 mph

Site Conditions

Light: Daylight
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 409 Swerving
V002 405 Failed to look properly
V002 602 Careless/Reckless/In a hurry

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car HGV	Going ahead other Turning Right	SW-NE SW-SE	Front None	Y N	63 48	Drv		Slight	M	63

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU04790/13	23/03/2013 Saturday 12:20	B2039 Jct B2215	B2039 OCKHAM ROAD 50 METRES NORTH OF B2215 PORTSMOUTH ROAD RIPLEY	V1 WAS WAITING AT R/ABOUT. V2 HAS HIT V1 IN REAR

Grid Ref: 506133 157461

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 60 mph

Site Conditions

Light: Daylight
R.S.C.: Wet/Damp
Weather: Raining with High Winds
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 405 Failed to look properly
V002 602 Careless/Reckless/In a hurry
V002 406 Failed to judge other person's path or

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Waiting to go ahead-held up	SW-NE	Back	N	55	Drv		Slight	M	55
Car	Slowing or Stopping	SW-NE	Front	N	66					

GU86402/16	08/07/2016 Friday 16:04	B2039 Jct B2039	B2039 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM ROAD NORTH OCKHAM	V1 TRAVELLING NE TO SW HAS CLIPPED THE N/S KERB AT SPEED CAUSING VEHICLE TO OVERTURN TWICE
------------	-------------------------------	-----------------------	---	--

Grid Ref: 506232 157381

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 60 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	Front	Y	68	Drv		Serious	F	68

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU15838/14	05/06/2014 Thursday 17:54	B2039 Jct C38	B2039 OCKHAM ROAD NORTH AT JUNCTION WITH OCKHAM LANE OCKHAM	V1 HAS FAILED TO GIVE WAY AT JUNCTION AND COLLIDED WITH V2 ON MAIN ROAD.

Grid Ref: 507125 156651

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 302 Disobeyed Give Way or Stop sign or
V001 706 Vision affected by dazzling sun
V001 702 Vision affected by vegetation

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Turning Right	NE-SW	O/side	N	54					
Van/LGV	Going ahead right hand bend	SW-E	N/side	N	31	Drv		Slight	M	31

GU31076/15	24/10/2015 Saturday 22:30	B2039 Jct C38	B2039 OCKHAM ROAD JUNCTION WITH OCKHAM LANE OCKHAM	V1 WITH A 5 OCCUPANT HAS DRIVEN FROM OCKHAM LANE WHEN LOST CONTROL AND COLLIDED WITH A TREE
------------	---------------------------------	---------------------	--	---

Grid Ref: 507124 156652

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: DARK-Street lighting Unk
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 502 Impaired by drugs (illicit or medicinal)

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	E-W	Front	N	40	Drv		Slight	M	40
						Pas		Slight	M	23
						Pas		Slight	M	21
						Pas		Slight	M	18
						Pas		Slight	M	21

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU55025/17	27/01/2017 Friday 17:11	B2039 Jct C38	B2039 OCKHAM ROAD NORTH AT JUNCTION WITH OCKHAM LANE OCKHAM Grid Ref: 507131 156651	VEHICLE TWO HAS BEEN TRAVELLING NORTH ALONG OCKHAM ROAD NORTH FROM THE RIPLEY DIRECTION. VEHICLE ONE HAS COME TO THE JUNCTION FROM OCKHAM LANE. VEHICLE ONE HAD PULLED OUT INTO THE PATH OF VEHICLE TWO CAUSING THE RIDER TO FALL TO THE FLOOR.

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: DARK-No street lights
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 501 Impaired by alcohol
V001 405 Failed to look properly

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Starting	NE-W	Front	N	38					
P/C	Going ahead other	W-E	N/side	N	56	Drv		Slight	M	56

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU68022/12	31/01/2012 Tuesday 13:10	B2039 Jct D	B2039 OCKHAM ROAD NORTH WEST OF ALMS HEATH OCKHAM SURREY Grid Ref: 507502 156484	V3 TRAV E HIT VAN PUSHING V1/V2 INTO DITCH. V3 FTS

Jct Type: Junction - more than 4 arms
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: LIGHT-No Street lights
R.S.C.: Wet/Damp
Weather: Other weather
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 306 Exceeding speed limit
V001 402 Junction Restart
V001 403 Poor turn or manoeuvre
V001 406 Failed to judge other person's path or
V001 403 Poor turn or manoeuvre

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Starting	NE-NW	O/side	N	48	Drv		Slight	M	48
Car	Going ahead right hand bend	NW-S	N/side	N	42	Drv		Slight	M	42
HGV	Going ahead right hand bend	NW-S	N/side	N	99					

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU06852/16	13/09/2016 Tuesday 16:17	B2039 Jct D	B2039 OCKHAM ROAD AT JUNCTION WITH ALMS HEATH OCKHAM Grid Ref: 507516 156459	V1 STOPPED WITH TRAFFIC. V2 BEHIND V1 AND BEGUN SLOWING TO STOP. V3 HAS FAILED TO REACT AND COLLIDED WITH THE BACK OF V2 PUSHING IT INTO V1.

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V003 405 Failed to look properly
V003 510 Distraction outside vehicle

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Waiting to go ahead-held up	SE-NW	Back	N	41					
Car	Slowing or Stopping	SE-NW	Back	N	25	Drv		Slight	F	25
Car	Going ahead left hand bend	SE-NW	Front	N	38					

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU27975/15	15/07/2015 Wednesday 18:18	B2039	B2039 OCKHAM ROAD NORTH OCKHAM Grid Ref: 508319 155513	V2 HAS OVERTAKEN V1 HIT A BUMP AND COME OFF BIKE

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 40 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 602 Careless/Reckless/In a hurry
V002 607 Inexperience with type of vehicle

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	SE-NW	None	N	50					
M/C>500	O/taking moving Veh on o/side	E-W	N/side	N	26	Drv		Serious	M	26

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU05159/13	02/04/2013 Tuesday 17:29	B2215	B2215 HIGH STREET RIPLEY Grid Ref: 505399 156887	V1 STARTED TO TURN R. V2 HAS APPROACHED AND REFUSED TO GIVE WAY TO V1 AND STARTED TO MANOUVRE AROUND V1 WHILST V1 MOVED FORWARD TO JOIN ONCOMING TRAFFIC. V2 THEN COLLIDED WITH V1

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Turning Right	NW-SW	Front	N	23	Drv		Slight	M	23
Car	Going ahead other	SW-NE	Front	N	44	Drv		Slight	M	44

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
WO28906/15	25/08/2015 Tuesday 17:15	B2215	B2215 HIGH STREET OUTSIDE THE TALBOT INN RIPLEY Grid Ref: 505404 156889	V1 COLLIDED WITH V2 AND V3 WHICH WERE PARKED AT THE SIDE OF THE ROAD.

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 204 Defective steering or suspension

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	Front	N	53	Drv		Slight	F	53
Car	Parked	Parked	Back	N						
Car	Parked	Parked	Front	N						

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU09473/13	24/09/2013 Tuesday 16:48	B2215	B2215 HIGH STREET RIPLEY	V1 HAS STRUCK PARKED V2 WHICH IN TURN HAS BEEN PUSHED INTO PARKED V3

Grid Ref: 505327 156854

Jct Type: ~Not at jct(or 20m from)

Jct Control:

Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly
V001 706 Vision affected by dazzling sun

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	Front	Y	30	Drv		Slight	M	30
Car	Parked	Parked	Back	N	85					
Car	Parked	Parked	Front	N	67					

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU11032/13	27/11/2013 Wednesday 00:44	B2215	B2215 HIGH STREET 50 METRES NORTH OF ROSE LANE RIPLEY	V1 WAS DRIVING ALONG AND HAS HIT PEDESTRIAN WHO HAS CHANGED DIRECTION

Grid Ref: 505238 156803

Jct Type: ~Not at jct(or 20m from)

Jct Control:

Speed Limit: 30 mph

Site Conditions

Light: DARK-Street Lighting -LIT
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

C001 806 Pedestrian impaired by alcohol
C001 802 Pedestrian failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	O/side	N	51	Ped	Stat	Serious	M	38

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU17102/14	23/07/2014 Wednesday 07:40	B2215 Jct D	B2215 OUTSIDE 'THE RIPLEY FLORIST' HIGH STREET 20 METRES NORTHEAST OF ROSE	PEDESTRIAN ON CROSSING WHEN IT BY V1 WHO FTS

Grid Ref: 505223 156790

Jct Type: 'T' or Staggered Jct
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Contributory Factors :

Light: Daylight
R.S.C.: Dry
Weather: Fine with High Winds
C/way Haz: ~None
Spec Cond: ~None

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	SW-NE	Front	N	99	Ped	SE	Slight	M	13

GU09414/13	23/09/2013 Monday 10:10	B2215 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 RIPLEY	V1S REAR TYRE LOST GRIP CAUSING MOTORCYCLIST TO LOSE CONTROL AND SLIDE ONTO ITS N/S
------------	-------------------------------	-----------------------	---	---

Grid Ref: 506128 157401

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Contributory Factors :

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
M/C>500	Going ahead other	SE-NW	N/side	Y	36	Drv		Serious	M	36

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003

Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU15564/14	27/05/2014 Tuesday 16:29	B2215 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM ROAD OCKHAM	V1 PULLS INTO PATH OF V2 ON LEAVING R/A

Grid Ref: 506099 157389

Jct Type: Roundabout
 Jct Control: Give Way or Uncontrolled
 Speed Limit: 60 mph

Site Conditions

Light: Daylight
 R.S.C.: Dry
 Weather: Fine (no high wind)
 C/way Haz: ~None
 Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly
 V001 509 Distraction in vehicle

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	Front	N	21					
Car	Going ahead other	SW-NE	Front	N	38	Drv		Slight	F	38

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU54529/17	02/02/2017 Thursday 08:22	B2215 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2029 OCKHAM ROAD NORTH RIPLEY	V1 TRAVELLING NORTH ALONG PORTSMOUTH ROAD WHERE IT HAS GONE THE WRONG SIDE OF THE KEEP LEFT ISLAND AND JOINED THE ROUNDAABOUT THE WRONG WAY WHEN V2 HAS COME EAST ROUND THE ROUNDAABOUT AND HIT THE FRONT OF V1.

Grid Ref: 506117 157401

Jct Type: Roundabout
 Jct Control: Give Way or Uncontrolled
 Speed Limit: 40 mph

Site Conditions

Light: Daylight
 R.S.C.: Wet/Damp
 Weather: Fine (no high wind)
 C/way Haz: ~None
 Spec Cond: ~None

Contributory Factors :

V001 403 Poor turn or manoeuvre
 V001 606 Inexperience of driving on the left

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead right hand bend	SW-SE	Front	N	42	Drv		Slight	F	42
Car	Turning Left	SE-SW	Front	N	38					

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU68505/12	26/02/2012 Sunday 11:16	B2215 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM ROAD RIPLEY Grid Ref: 506112 157427	V1 (CAR) TRAV ALONG PORTSMOUTH RD TOWARDS R/A WITH WISLEY ON SLIP TO A3. V2 (PEDAL CYCLE) NEGOTIATING R/A. V1 COLLIDES WITH V2 THEN STOPS THEN DRIVES OFF AT SPEED WITHOUT LEAVING DETAILS

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: LIGHT-Street lights present
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 602 Careless/Reckless/In a hurry
V001 405 Failed to look properly
V001 406 Failed to judge other person's path or

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	S-N	Front	N						
P/C	Going ahead right hand bend	E-N	N/side	N	43	Drv		Slight	M	43

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU01941/12	18/12/2012 Tuesday 06:55	B2215 Jct A3	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM R/ABOUT RIPLEY Grid Ref: 506110 157424	V1 STOPPED AT THE GIVE WAY LINE BEFORE ENTERING THE R/ABOUT. V2 COLLIDED INTO THE REAR OF V1

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: DARK-Street Lighting -LIT
R.S.C.: Wet/Damp
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 406 Failed to judge other person's path or
V002 308 Following too close

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Slowing or Stopping	SW-NE	Back	N	48					
Car	Going ahead other	SW-NE	Front	N	31	Drv		Slight	F	31

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU85523/16	10/07/2016 Sunday 08:58	B2215 Jct B2039	B2215 PORTSMOUTH ROAD AT JUNCTION WITH B2039 OCKHAM ROAD NORTH OCKHAM	V1 HAS COLLIDED WITH V2 ON R/A

Grid Ref: 506112 157425

Jct Type: Roundabout
Jct Control: Give Way or Uncontrolled
Speed Limit: 40 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 405 Failed to look properly

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Van/LGV	Starting	SW-NE	Front	N	48					
P/C	Going ahead right hand bend	SE-NE	N/side	N	46	Drv		Slight	M	46

CASUALTIES:

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU44321/16	01/02/2016 Monday 17:45	B2215	B2215 PORTSMOUTH ROAD RIPLEY	V1 DRIVING ALONG PORTSMOUTH ROAD HAS FOR UNKNOWN REASON CLIPPED THE KERB RESULTING IN THE VEHICLE HITTING A WALL.

Grid Ref: 505699 156945

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: DARK-Street lighting Unk
R.S.C.:
Weather: ~Unknown
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

VEHICLES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Van/LGV	Going ahead left hand bend	W-NE	N/side	N	50	Drv		Slight	M	50

CASUALTIES:

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU14136/16	02/10/2016 Sunday 09:40	B2215	B2215 PORTSMOUTH ROAD RIPLEY	V2 FROM NORTH EAST BOUND WHEN TURNED RIGHT V2 HIT FROM BEHIND

Grid Ref: 506064 157287

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V002 405 Failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	NE-SW	Back	N	78					
Car	Going ahead other	NE-SW	Front	N	99	Drv		Slight	M	99

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU25011/15	17/05/2015 Sunday 09:00	C38	OCKHAM LANE OCKHAM	V1 STOPPED BEHIND CYCLIST WITH A PUNCTURE. V2 COLLIDED WITH R/O V1

Grid Ref: 508672 157193

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 40 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: Pedestrian in C/way -
Spec Cond: ~None

Contributory Factors :

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Waiting to go ahead-held up	NE-SW	Back	N	99					
P/C	Going ahead other	NE-SW	Front	N	40	Drv		Slight	M	40

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU70892/12	01/06/2012 Friday 11:15	C38	GUILES HILL LANE AT JUNCTION WITH GUILESHILL FARM RIPLEY	CYCLIST (V1) OVERTAKEN BY V2. V2 CLOSED HIM DOWN. IN TURN CAUSED V1 TO FALL OFF.

Grid Ref: 506457 156070

Jct Type: ~Not at jct(or 20m from)

Jct Control:

Speed Limit: 30 mph

Site Conditions

Light: LIGHT-Street lights present

R.S.C.: Dry

Weather: Fine (no high wind)

C/way Haz: ~None

Spec Cond: ~None

Contributory Factors :

V002 407 Too close to cyclist horse rider or

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
P/C	Going ahead other	NE-SW	O/side	N	19	Drv		Slight	M	19
Car	O/taking moving Veh on o/side	NE-SW	N/side	N	55					

GU71421/12	13/06/2012 Wednesday 11:48	C42 Jct C43	HORSLEY ROAD AT JUNCTION WITH HOWARD ROAD EFFINGHAM	V1 TRAVELLING ALONG HORSLEY ROAD. C2 CROSSING ROAD FROM HOWARD ROAD TOWARDS OLD LANE. V1 COLLIDED WITH C2.
------------	----------------------------------	-------------------	---	--

Grid Ref: 510208 156029

Jct Type: 'T' or Staggered Jct

Jct Control: Give Way or Uncontrolled

Speed Limit: 30 mph

Site Conditions

Light: LIGHT-Street lights present

R.S.C.: Dry

Weather: Fine (no high wind)

C/way Haz: ~None

Spec Cond: ~None

Contributory Factors :

C002 802 Pedestrian failed to look properly

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead other	N-S	Front	N	65	Drv		Slight	F	65
						Ped	W	Serious	M	17

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..

ACCIDENT

Report for period : 01/01/2012 to 30/04/2017

Menu Selection: Accidents in Query Site-2003
Criteria: Surrey Roads Accidents

Site Location: Area around Wisley Airfield

Site Ref: DJB/TI/WISAF

Accident Ref No.	Date Day/Time	Road No.	Location	Description of Accident
GU08734/16	13/09/2016 Tuesday 10:02	C42	FOREST ROAD EAST HORSLEY	V1 HAS CROSSED CARRIAGEWAY AND COLLIDED WITH V2.

Grid Ref: 509892 155297

Jct Type: ~Not at jct(or 20m from)
Jct Control:
Speed Limit: 30 mph

Site Conditions

Light: Daylight
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 403 Poor turn or manoeuvre

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
Car	Going ahead left hand bend	NW-SE	Front	N	33					
Car	Going ahead right hand bend	SE-NW	Front	N	69	Drv		Slight	F	69

GU68447/12	25/02/2012 Saturday 23:26	C42	OUTSIDE MILLSTONE FOREST ROAD EFFINGHAM JUNCTION.	V2 HAS HIT V1 (MOTOR CYCLE) WHO WAS TURNING LEFT INTO DRIVEWAY
------------	---------------------------------	-----	---	--

Grid Ref: 510053 155683

Jct Type: Private Dr/Entrance
Jct Control: Give Way or Uncontrolled
Speed Limit: 30 mph

Site Conditions

Light: DARK-Street Lighting -LIT
R.S.C.: Dry
Weather: Fine (no high wind)
C/way Haz: ~None
Spec Cond: ~None

Contributory Factors :

V001 403 Poor turn or manoeuvre
V001 404 Failed to signal/Misleading signal
V002 405 Failed to look properly
V002 406 Failed to judge other person's path or

VEHICLES:

CASUALTIES:

Type	Manoeuvres	Dir	Impact	Skid	Drv Age	Class	Pdir	Severity	Sex	Age
M/C>500	Turning Left	NE-SE	None	N	23	Drv		Slight	M	23
Car	Slowing or Stopping	NE-SW	Front	N	80					

ACCIDENT selected where: Road1Class<>'M'and Road1Suffix<>'T'

Report Date
19/06/2017 ..